



Technical Tips

by William J. Diamond (Bill), WROT

Some KWM2's exhibit an audio howl or feedback at high volume levels. I found that by moving the caps to a slightly different physical location on the audio tubes eliminated or reduced the problem. It would appear that lead dress is very important to avoid ground loops and oscillations.